

Community Living Arrangement Inspection Report Summary

Residence: NEW HARTFORD

Inspection Date: 8/19/2020

Address: 103 Highland Avenue New Hartford CT 06057

License Number: DSLA.002492

DDS Region: WR

Agency: OAK HILL

Inspection Type: Standard

Inspection Report Citations Were Reported In The Following Regulatory Areas:

11b - Fire Marshal's certificate

11g - Fire extinguishers

12b - Emergency response training/monthly fire drills

17h - The OPS shall be reviewed at least minimally quarterly

17j - Data collected on programs

19a2 - Individual financial records

Community Living Arrangement Inspection Report Summary

Residence:

Inspection Date:

Address:

License Number:

DDS Region:

Agency:

Inspection Type: Revisit

Inspection Report Citations Were Reported In The Following Regulatory Areas:

Community Living Arrangement Inspection Report Summary

Residence:

Inspection Date:

Address:

License Number:

DDS Region:

Agency:

Inspection Type: Revisit

Inspection Report Citations Were Reported In The Following Regulatory Areas: